

Pin	Signal Name	Pin	Signal Name
5	CS (CTS)	18	Not used
6	DR (DSR)	19	Not used
7	GND (Logic)	20	ER (DTR)
8	Not used	21	Not used
9	Not used	22	Not used
10	Not used	23	Not used
11	Not used	24	Not used
12	Not used	25	Not used
13	Not used		

Cable Connection

The cable pin assignment of the serial interface connector from the 25-pin plotter connector to the 9-pin computer connector or the 25-pin computer connector is described below.

